

INSTALL SHOWER HEAD

Turn off hot and cold water CAUTION supplies before beginning.

- Thread SHOWER HEAD (1) hand tight onto SUPPLY NIPPLE (2). FIG. 1.
- Level SHOWER HEAD (1). Mark the location of the three mounting holes. Remove SHOWER HEAD (1). FIG. 2.
- Drill three 1/8" diameter holes a minimum of 1-1/4" deep. With a hammer tap the three ANCHORS (3) (not supplied) flush with face of the finished wall. FIG. 3.
- Apply TEFLON TAPE (4) to SUPPLY NIPPLE (2). FIG. 4.
- Thread SHOWER HEAD (1) onto SUPPLY NIPPLE (2). Use a strap wrench to protect finish. Fully tighten and check for level. Turn shower on and check for leaks. Tighten if required. **FIG. 5.**
- Install the MOUNTING SCREWS (5) (not supplied) and fully tighten to secure the SHOWER HEAD (1) to the wall. FIG. 5.





