

CLEANING CODES FOR FABRICS

CODE "S" CARE METHOD

TO PREVENT OVERALL SOIL, FREQUENT VACUUMING OR LIGHT BRUSHING TO REMOVE DUST AND GRIME IS RECOMMENDED. SPOT CLEAN USING A MILD WATER-FREE SOLVENT OR DRY CLEANING PRODUCT. CLEAN ONLY IN A WELL VENTILATED ROOM AND AVOID ANY PRODUCT CONTAINING CARBON TETRACHLORIDE WHICH IS HIGHLY TOXIC. PRETEST SMALL AREA BEFORE PROCEEDING. CLEANING BY A PROFESSIONAL FURNITURE CLEANING SERVICE ONLY IS RECOMMENDED.

CODE "W" CARE METHOD

USE A WATER- BASED UPHOLSTERY CLEANER ONLY.

CODE "WS" CARE METHOD

TO PREVENT OVERALL SOIL, FREQUENT VACUUMING OR LIGHT BRUSHING TO REMOVE DUST AND GRIME IS RECOMMENDED. SPOT CLEAN WITH A MILD SOLVENT, AN UPHOLSTERY SHAMPOO, OR THE FOAM FROM A MILD DETERGENT. WHEN USING A SOLVENT OR DRY CLEANING PRODUCT, FOLLOW INSTRUCTIONS CAREFULLY AND CLEAN ONLY IN A WELL VENTILATED ROOM. AVOID ANY PRODUCT WHICH IS HIGHLY TOXIC. IF USING EITHER METHOD, PRETEST A SMALL AREA BEFORE PROCEEDING. USE A PROFESSIONAL FURNITURE CLEANING SERVICE WHEN AN OVERALL SOILED CONDITION HAS BEEN REACHED.

CODE "SW" CARE METHOD

SPOT CLEAN WITH UPHOLSTERY SHAMPOO, FOAM FROM A MILD DETERGENT, OR MILD DRY CLEANING SOLVENT. PRETEST A SMALL, INCONSPICUOUS AREA BEFORE PROCEEDING. DO NOT SATURATE. PILE FABRICS MAY REQUIRE BRUSHING WITH A NON-METALLIC, STIFF BRISTLE BRUSH TO RESTORE APPEARANCE. HOT WATER EXTRACTION OR STEAM CLEANING IS NOT RECOMMENDED. CUSHION CASINGS SHOULD NOT BE REMOVED AND LAUNDERED OR DRY CLEANED SEPARATELY. TO PREVENT OVERALL SOILING, FREQUENT VACUUMING OR LIGHT BRUSHING WITH A NON-METALLIC, STIFF BRISTLE BRUSH TO REMOVE DUST AND GRIME IS RECOMMENDED. WHEN CLEANING A SPILL, BLOT IMMEDIATELY TO REMOVE SPILLED MATERIAL. CLEAN SPOTS OR STAINS FROM THE OUTSIDE TO THE MIDDLE OF THE AFFECTED AREA TO PREVENT CIRCLING. USE A PROFESSIONAL FURNITURE CLEANING SERVICE WHEN AN OVERALL SOILED CONDITION HAS BEEN REACHED.