
## **ASSEMBLY INSTRUCTIONS**

## RECTANGULAR END TABLE


Step 3

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.


Step 1: Put table top A upside down on a protective smooth surfcae, and attach metal legs B and then stretchers C;



Step 2: Put the bottom shelf part (D) on top of the (B&C) Metal legs and locate the threaded inserts into the holes in bottom panel and then fasten the bolts.



| PARTS LIST:    |                     |        |          |          |
|----------------|---------------------|--------|----------|----------|
| NO.            | Description         | Sketch |          | Quantity |
| A              | Тор                 |        |          | 1pc      |
| В              | Metal Leg           |        |          | 2pcs     |
| С              | Metal Leg           |        |          | 2pcs     |
| D              | Bottom shelf        |        |          | 1pc      |
| HARDWARE LIST: |                     |        |          |          |
| NO.            | Description         |        | Sketch   | Quantity |
| Е              | Allen Wrench 4 MM   |        |          | 1pc      |
| F              | BoltØ4"*16MM        |        | <b>•</b> | 12pcs    |
| G              | Lock WasherØ4"      |        | 0        | 12pcs    |
| Н              | Flat WasherØ4"*17MM |        |          | 12pcs    |



MADE IN CHINA